



[VW GTI Forum](#) / [VW Rabbit Forum](#) / [VW R32 Forum](#) / [VW Golf Forum](#) - [Golfmkv.com](#) >
[Technical Discussions](#) > [Wheels / Tires](#) / [Suspension](#) / [Brakes](#) sponsored by The Tire Rack
ABS Problem



Support GolfMKV by clicking this link to do your tirerack shopping, THANKS!



POST REPLY

[Thread Tools](#) [Search this Thread](#) [Rate Thread](#)

11-03-2009, 10:24 PM

g60 corrado 91

 GolfMKV Elite

 Drives: 2006 Candy White GTI
 Pkg 1 6MT
 Join Date: Oct 2006
 Location: IL
 Posts: 19,031

[View g60 corrado 91's Garage](#)

ABS Problem

Earlier today my **ABS** light came on after I did the activation of the **ABS** and all that in the steps. Here's what the VAG-COM scan said.

Address 03: **ABS** Brakes Labels: 1K0-907-379-MK60-F.lbl
 Part No SW: 1K0 907 379 AA HW: 1K0 907 379 AA
 Component: ESP FRONT MK60 0102
 Revision: 00H13001
 Coding: 0021122
 Shop #: WSC 01279 785 00200

1 Fault Found:
 01486 - **System Function Test Activated**
 000 - -

I tested my car out and the **ABS** works properly with the ESP button both on and off. The ESP works with the ESP button on and doesn't switched off. Basically everything is acting normal including traction control when it's on.

The **ABS** light stays on all the time, not flashing or anything. When I depress the brake pedal hard while idling, the ESP light will start fla Then it goes off after awhile unless I depress the brakes hard again. The ESP button stays on constantly if I've depressed the ESP Off bu

I've tried searching both her and on the vortex with no luck. I'm hoping I didn't fry the module but I don't think I could have if everythin

Thanks guys.

Edit: I suppose I should've searched Google. I'm not sure if this is the problem, I'll have to check it out tomorrow.

<http://forums.audiworld.com/showthread.php?t=1578124>

From S4wiki:

"How do I cycle the **ABS** pump with a VAG when flushing/bleeding brake fluid?

[03 - **ABS** Brakes]
 [Basic Settings - 04]
 Group 002
 [Go!]

If you throw a "01486 **ABS test activated**" the cycle did not complete correctly, and the **ABS test** is still in progress. Roll the car 15-20 hard. Then, hold the steering wheel 10 degrees from center while moving in a circle for at least 4 seconds. Do each direction separately (circle). Do not exceed ~39mph.

If this does not work, you may have to physically realign the steering angle sensor back to within +/- 7.5 degrees of zero via the tie rods calibration procedure above."

Unitronic Stg 2+ K04

[Chicago VW Organization](#)

[My flickr](#)

Quote:

Originally Posted by [tree_hugger](#)
 "hey yo bish, nice shoes, wanna fuck?"

Quote:

Originally Posted by [TwentyonePSI](#)
 One day you're banging a chick with a fucked up fake tit, 6 months later you're banging a chick with no legs. It's a slippery slope.



POST REPLY

Quick Reply

 Message:

B

I

U

A

Options

☐ Quote message in reply?

☒ Show your signature

Post Quick Reply

Go Advanced

« [Previous Thread](#) | [Next Thread](#) »

Posting Rules

- You **may** post new threads
- You **may** post replies
- You **may** post attachments
- You **may** edit your posts

BB code is **On**
Smilies are **On**
[IMG] code is **On**
HTML code is **Off**

Forum Rules

Forum Jump

Wheels / Tires / Suspension / Brakes sponsored by The Tire Rack [Go](#)

All times are GMT -4. The time now is 12:57 AM.

[Contact Us](#) - [VW GTI Forum](#) / [VW Rabbit Forum](#) / [VW R32 Forum](#) / [VW Golf Forum](#) - [Golfmkv.com](#) - [Archive](#) - [Top](#)

Powered by vBulletin® Version 3.8.0
Copyright ©2000 - 2012, Jelsoft Enterprises Ltd.