

Reply With Quote

flieger 🛛

Member



 Join Date:
 Jun 28th, 2000

 Location:
 Colorado Springs, CO

 Posts:
 6,028

 Vehicles:
 2015 Q5 3.0T Stg 2+, 2012 CW Golf R OEM+, 1983 Rabbit GTI Sport, 1969 Transporter

👥 Originally Posted by **03_uni-B** 🕎

Some good looking runs. How did you compare to the others at the event?

I was consistently 3rd in my run group (Purple), if I'd been in the Green or Orange open passing groups I would have been about mid pack as most of those cars were not daily drivers and we're all basically track prepped cars.

R Originally Posted by **TwoPugs**

I thought I pushed my car on the track, I cannot imagine doing 140 mph and then braking to 36 mph into the corner. Very impressive and gives the rest of us something to aim for.

I have to say that this weekend proved that the VWR BBK was well worth the money spent on it along with the Akebono rear pads. The kit itself never failed me throughout the three days and was very easy to tell where the total braking threshold was. I do believe that I need to upgrade my brake/clutch fluid reservoir from the factory plastic unit to something else because it did leak some fluid at one point during the week while hot. The cap was tight and properly installed...so I'll need to investigate my options.

Originally Posted by EZ 🔟

Nice!

Thanks

2015 Audi Q5 3.0T | 2012 CW Golf R Stage 3 OEM+ | 1983 Rabbit GTI Sport | 1969 Kombi paypal.me/waterwerks

flieger •

Member



 Join Date:
 Jun 28th, 2000

 Location:
 Colorado Springs, CO

 Posts:
 6,028

 Vehicles:
 2015 Q5 3.0T Stg 2+, 2012 CW Golf R OEM+, 1983 Rabbit GTI Sport, 1969 Transporter
 MK7 Climatronic and Auto Recirculation Sensor wiring for MK6 install and upgrade

Loss of sound through RNS-510 when using Bluetooth for phone or streaming audio

So yesterday, I figured out that while I was installing the auto dimming mirror harness and reconfiguring the fuse box to clean it up, I somehow manage to tug on the radio harness. This uncliped part of the harness that controls the Bluetooth module under the Passenger seat that is required when running the RNS-510 Navigation. After a handful of text messages and a phone call with Peter, he suggested that I check the harness as the end effect was that I had extremely week sound coming through the left front speaker and no use of the voice activation or the overhead mic during handsfree phone use.

Last night as I was checking things I ran up against a time barrier with going to a previously planned dinner with friends, so I was frustrated and completely missed the loose plug as I was only focusing on single wires. This morning I got up, knowing that I had plenty of time to dig in to the dash, I set out to find the issue. Lucky enough for me it was the first thing I pulled which was the primary large black square connector on the back of the radio. Once I had it out of the radio I found that the small square black connector had back itself out just enough to not make contact properly with the pins in the radio and was the cause of the issue I was having. Very glad that was a simple fix and not something that was going to require a new harness or part.

MK7 Climatronic and Auto Recirculation Sensor wiring for MK6 install and upgrade (since I've been asked a few time now about this)

While I was in there I figured I'd also copy the wiring to the Climatronic harness that is required if you decide to install the MK7 panel with the Auto Recirculation button and the accompanying sensor under the hood. If you look at the Bold-Sport site they show you where the sensor is supposed to go. This requires you to remove the rain tray and wiper arms. You will see a 2" tall rubber grommet off to the left of the air intake duct, and this is where you will fish the wiring through to the cabin of the car. once you have it routed to the back of the new MK7 Climatronic control panel this is how you will wire it into the system, please note that there is absolutely no moving of pins required, only adding one in the plug and splicing into two.

#503

Reply

Reply With Quote

Reply

05-03-2015 05:42 PM

#504

	NOTEIf you have the harness from Bold-Sport the pin/wires should be:
	Pin #1: Black Pin #2: Brown Pin #3: Green (striped)
	Quality Sensor Wiring at Climatronic control head
	"C" Connector (Largest black connector on right side of control head for MK7): Pin 1 from Sensor is Power goes to Pin 20[/B][B] [B](splice into this wire) Pin 2 from Sensor is Ground goes to Pin 19 (splice into this wire) Pin 3 from Sensor is Signal goes into Pin 4 hole (this is an open hole)
	There is also no coding once you have the new panel in place and the wiring completed, if you previously installed the panel before having the wiring and sensor you would have had a code in 08-Auto HVAC that should read like below, you will only need to clear the code.
	9479189 - Signal Line for Air Quality Sensor B10A4 15 [009] - Open or Short to Plus
	Hope this clears up any confusion from folks that have looked at the various MK5 DIY's for upgrade to a MK6/7 Climatronic panel.
	Last edited by flieger; 05-03-2015 at 05:47 PM.
	2015 Audi Q5 3.0T 2012 CW Golf R Stage 3 OEM+ 1983 Rabbit GTI Sport 1969 Kombi paypal.me/waterwerks
	Reply With Quote
karlscheible • Member	05-04-2015 12:28 AM Reply #505
Join Date: Dec 10th, 2012 Posts: 127	Much better! I see 2-3 more seconds easily. Email me and we can cover the few areas.
	Reply With Quote
flieger • Member	05-04-2015 12:54 AM
	Q Originally Posted by karlscheible
MOTOR	Much better! I see 2-3 more seconds easily. Email me and we can cover the few areas.
Join Date:Jun 28th, 2000Location:Colorado Springs, COPosts:6,028Vehicles:2015 Q5 3.0T Stg 2+,2012 CW Golf R OEM+, 1983 RabbitGTI Sport, 1969 Transporter	Will do Karl! Glad we had the chance to share a garage with you and your father. The new Viper is absolutely stunning. Looking forward to another track day.
	2015 Audi Q5 3.0T 2012 CW Golf R Stage 3 OEM+ 1983 Rabbit GTI Sport 1969 Kombi paypal.me/waterwerks
	Reply With Quote

05-04-2015 10:20 AM

#507

Reply

👥 Originally Posted by flieger 🔟

Loss of sound through RNS-510 when using Bluetooth for phone or streaming audio

So yesterday, I figured out that while I was installing the auto dimming mirror harness and reconfiguring the fuse box to clean it up, I somehow manage to tug on the radio harness. This uncliped part of the harness that controls the Bluetooth module under the Passenger seat that is required when running the RNS-510 Navigation. After a handful of text messages and a phone call with Peter, he suggested that I check the harness as the end effect was that I had extremely week sound coming through the left front speaker and no use of the voice activation or the overhead mic during handsfree phone use.

Last night as I was checking things I ran up against a time barrier with going to a previously planned dinner with friends, so I was frustrated and completely missed the loose plug as I was only focusing on single wires. This morning I got up, knowing that I had plenty of time to dig in to the dash, I set out to find the issue. Lucky enough for me it was the first thing I pulled which was the primary large black square connector on the back of the radio. Once I had it out of the radio I found that the small square black connector had back itself out just enough to not make contact properly with the pins in the radio and was the cause of the issue I was having. Very glad that was a simple fix and not something that was going to require a new harness or part.

MK7 Climatronic and Auto Recirculation Sensor wiring for MK6 install and upgrade (since I've been asked a few time now about this)

While I was in there I figured I'd also copy the wiring to the Climatronic harness that is required if you decide to install the MK7 panel with the Auto Recirculation button and the accompanying sensor under the hood. If you look at the Bold-Sport site they show you where the sensor is supposed to go. This requires you to remove the rain tray and wiper arms. You will see a 2" tall rubber grommet off to the left of the air intake duct, and this is where you will fish the wiring through to the cabin of the car. once you have it routed to the back of the new MK7 Climatronic control panel this is how you will wire it into the system, please note that there is absolutely no moving of pins required, only adding one in the plug and splicing into two.

****NOTE****If you have the harness from Bold-Sport the pin/wires should be:

Pin #1: Black Pin #2: Brown Pin #3: Green (striped)

Quality Sensor Wiring at Climatronic control head

"C" Connector (Largest black connector on right side of control head for MK7): Pin 1 from Sensor is Power goes to Pin 20[/B][B] [B](splice into this wire) Pin 2 from Sensor is Ground goes to Pin 19 (splice into this wire)

Pin 3 from Sensor is Signal goes into Pin 4 hole (this is an open hole)

There is also no coding once you have the new panel in place and the wiring completed, if you previously installed the panel before having the wiring and sensor you would have had a code in 08-Auto HVAC that should read like below, you will only need to clear the code.

9479189 - Signal Line for Air Ouality Sensor B10A4 15 [009] - Open or Short to Plus

Hope this clears up any confusion from folks that have looked at the various MK5 DIY's for upgrade to a MK6/7 Climatronic panel.

I'm glad the issue with your Bluetooth sound loss was this simple and didn't require replacing the wire harness. 😀

-Peter

Reply With Quote

flieger o

Member

#508 05-04-2015 03:34 PM Reply



Sep 29th, 2000

2012 R CW 4Dr

Chicago

936

Join Date:

Location: Posts:

Vehicles:

S

NOTOR	Q Originally Posted by Peteski
Join Date: Jun 28th, 2000 Location: Colorado Springs, CO Posts: 6,028	-Peter
Vehicles: 2015 Q5 3.0T Stg 2+, 2012 CW Golf R OEM+, 1983 Rabbit GTI Sport, 1969 Transporter	As am I Peter! Had I not had someone in my ear originally when I was going through things, I'd have likely found it from the start but in the end it's secure again and there is no need to pull on wires any time soon.
	2015 Audi Q5 3.0T 2012 CW Golf R Stage 3 OEM+ 1983 Rabbit GTI Sport 1969 Kombi paypal.me/waterwerks
	Reply With Quote
Ellom •	05-04-2015 04:42 PM Reply #509
Member Join Date: Aug 15th, 2012 Location: Portland, OR Posts: 266 Vehicles: 2013 Golf R	Thanks for clearing up the AQS for myself and anyone else.
	2013 Golf R 4 Door Loaded / Stage 2+ / UNITEDMOTORSPORT Stage 2 Loaded / VWR CAI / SPM TBE (Track DP) / APR HPFP / R8 Coilpack / BFI Clean CC / P3Cars Boost Gauge (Red/White)
	Reply With Quote
flieger • Member	05-04-2015 08:43 PM Reply #510
	Q Originally Posted by Ellom
MOTOR	Thanks for clearing up the AQS for myself and anyone else.
Join Date:Jun 28th, 2000Location:Colorado Springs, COPosts:6,028Vehicles:2015 Q5 3.0T Stg 2+,2012 CW Golf R OEM+, 1983 RabbitGTI Sport, 1969 Transporter	No worries! Glad to help out where I can. 🗐 🕅
	2015 Audi Q5 3.0T 2012 CW Golf R Stage 3 OEM+ 1983 Rabbit GTI Sport 1969 Kombi paypal.me/waterwerks
	Reply With Quote
flieger • Member	05-12-2015 10:11 AM Reply #511
	Hmmwonder what's hiding in here 😈



Join Date:Jun 28th, 2000Location:Colorado Springs, COPosts:6,028Vehicles:2015 Q5 3.0T Stg 2+,2012 CW Golf R OEM+, 1983 RabbitGTI Sport, 1969 Transporter




	UNITED AIRLINES INC. BUT UNITED AIRLINES IN
	2015 Audi Q5 3.0T 2012 CW Golf R Stage 3 OEM+ 1983 Rabbit GTI Sport 1969 Kombi paypal.me/waterwerks Reply With Quote
	Reply with Quote
mrhythm Member Join Date: Sep 17th, 2006 Location: MD Posts: 360 Vehicles: 2011 Audi TTS Join Date: X	06-02-2015 06:13 PM Reply #512 Wide front fender? Sent from my iPad using Tapatalk Previous cars. 2012 VW Golf R, 2009 BMW 135i, 2007 Audi A3 S-line 3.2, 2004 Audi S4, 2002 Audi TT Roadster 225Q, 2000 VW GTI VR6, 1988 Toyota MR2 SC, 1992 Mitsubishi Galant VR4, 1988 Dodge Conquest TSI
	Reply With Quote
GTIMike1.8T • Member	06-02-2015 07:18 PM Reply #513
Join Date: Jan 15th, 2006 Location: Lilburn, GA Posts: 3,043 Vehicles: 370z	Image: Constrained by mrhythm Wide front fender? Sent from my iPad using Tapatalk with the rear arches they make too?
	Its only game why you heff to be mad

	Reply With Quote
flieger • Member	06-04-2015 07:39 AM Reply #514
	Image: Comparison of the second se
Join Date:Jun 28th, 2000Location:Colorado Springs, COPosts:6,028	Dingding! Time to allow for a wider overall track in the car.
Vehicles: 2015 Q5 3.0T Stg 2+, 2012 CW Golf R OEM+, 1983 Rabbit GTI Sport, 1969 Transporter	Image: Comparison of the state of the s
	Not planning on doing the rears as there is plenty of room in the back for wider rims/tires.
	2015 Audi Q5 3.0T 2012 CW Golf R Stage 3 OEM+ 1983 Rabbit GTI Sport 1969 Kombi paypal.me/waterwerks
	Reply With Quote
Oliker • Member Join Date: Feb 8th, 2007 Posts: 703	06-04-2015 02:26 PM Reply #515 Do you mind sharing where you got the fenders? Maybe price as well Nice car you have there!
	Reply With Quote
flieger • Member	06-05-2015 05:02 AM Reply #516
MOTOR PORT	R Originally Posted by oliker D Do you mind sharing where you got the fenders? Maybe price as well Nice car you have there!
Join Date:Jun 28th, 2000Location:Colorado Springs, COPosts:6,028Vehicles:2015 Q5 3.0T Stg 2+,2012 CW Golf R OEM+, 1983 RabbitGTI Sport, 1969 Transporter	I ordered them directly through Kerscher. They were relatively cheap until I get the bill for customswhich basically doubled the cost. I think I paid \$900ish for them when all was done.
	2015 Audi Q5 3.0T 2012 CW Golf R Stage 3 OEM+ 1983 Rabbit GTI Sport 1969 Kombi paypal.me/waterwerks
	Reply With Quote
DUBIclutch •	06-05-2015 07:55 PM Reply #517

Member Join Date: Apr 6th, 2012 Location: Pure MI Posts: 1,155 Vehicles: 1997 Acura Integra GSR (DC2) 5MT//2006 MKV GTI 2.0T FSI 6MT//2013 Golf R 6MT	George - Are you aware of what modifications are required to run the TTRS knuckles/spindles? Thanks in advance, DUB.
	Reply With Quote
flieger • Member	06-06-2015 06:35 AM Reply #518
	Q Originally Posted by DUBIclutch
MOTOR SPORT	George - Are you aware of what modifications are required to run the TTRS knuckles/spindles? Thanks in advance, DUB.
Join Date: Jun 28th, 2000 Location: Colorado Springs, CO Posts: 6,028 Vehicles: 2015 Q5 3.0T Stg 2+, 2012 CW Golf R OEM+, 1983 Rabbit GTI Sport, 1969 Transporter	I know that besides the milling that is supposed to be done on the uprights themselves, you also have to basically install the entire Polo Cup front end in the Golf R. It's not really a cheap process to run it. I've looked into in the past when I wanted to do the full VWR Cup widebody kit but after seeing that the kit really isn't built well and the amount of work to run it I chose not to do it. I'm going to do a set of Passat aluminum fronts to cut the weight down and not worry about the wider front track. I will be doing a set of wider rims for track events with the new Kerscher fenders I'm going to install.
	2015 Audi Q5 3.0T 2012 CW Golf R Stage 3 OEM+ 1983 Rabbit GTI Sport 1969 Kombi paypal.me/waterwerks
	Reply With Quote
DUBIclutch • Member	06-06-2015 06:59 PM Reply #519
Join Date: Apr 6th, 2012 Location: Pure MI	R Originally Posted by flieger
Posts: 1,155 Vehicles: 1997 Acura Integra GSR (DC2) 5MT//2006 MKV GTI 2.0T FSI 6MT//2013 Golf R 6MT	I know that besides the milling that is supposed to be done on the uprights themselves, you also have to basically install the entire Polo Cup front end in the Golf R. It's not really a cheap process to run it. I've looked into in the past when I wanted to do the full VWR Cup widebody kit but after seeing that the kit really isn't built well and the amount of work to run it I chose not to do it. I'm going to do a set of Passat aluminum fronts to cut the weight down and not worry about the wider front track. I will be doing a set of wider rims for track events with the new Kerscher fenders I'm going to install.
	Thanks for the reply. I assume running the Polo kit is required for extra clearance due to the wider track. I wonder if you would have issues, now that you'll be running the wide fenders?
	Reply With Quote
flieger • Member	06-08-2015 05:31 AM Reply #520
	Q Originally Posted by DUBIclutch
MOTOR	Thanks for the reply. I assume running the Polo kit is required for extra clearance due to the wider track. I wonder if you would have issues, now that you'll be running the wide fenders?
Join Date: Jun 28th, 2000 Location: Colorado Springs, CO	

Posts: 6,028 Vehicles: 2015 Q5 3.0T Stg 2+, 2012 CW Golf R OEM+, 1983 Rabbit GTI Sport, 1969 Transporter	Havent installed the new fenders yet, that's on the books for when I return from work in July. 🖓 🗒
	2015 Audi Q5 3.0T 2012 CW Golf R Stage 3 OEM+ 1983 Rabbit GTI Sport 1969 Kombi paypal.me/waterwerks Reply With Quote
flieger °	
Member	
NOOTOR NOOTOR	So it appears that this arrived at the shop for me while I've been gone, as well as a new surprise from Peter the Great $\overline{\mathfrak{W}}_{!}$
Join Date: Jun 28th, 2000 Location: Colorado Springs, CO Posts: 6,028 Vehicles: 2015 Q5 3.0T Stg 2+, 2012 CW Golf R OEM+, 1983 Rabbit	
GTI Sport, 1969 Transporter	



Cheddyruxpin •

Member

06-21-2015 02:46 PM

#522

Originally Posted by flieger



 Join Date:
 May 28th, 2007

 Location:
 CO

 Posts:
 119

 Vehicles:
 2012 Golf R / 07 GTI / 02 JETTA / 10 SVT RAPTOR /00 F150

 RAPTOR Jr.
 So it appears that this arrived at the shop for me while I've been gone, as well as a new surprise from Peter the Great \widetilde{v}



Ive got one sitting in the garage as well. Hoping to install it mid week. I got on a dyno yesterday to get a baseline prior to the install and put down some really respectable numbers given ambient temps and arid conditions. I plan on a second trip after I get the manifold on my car. I'm really interested to see the gains on your car. Need to get that sucker on the dyno.

2012 Golf R Deep Black~APR Stage 2+~APR HPFP~VWR Intake~VWR TBE~VWR Short Shifter~VWR Springs~VWR Subframe Mount~IE FDS Intercooler~HP Comp Controller~IE Intake Manifold~

Reply With Quote

Member



Join Date: Jun 28th, 2000 Location: Colorado Springs, CO Posts: 6,028 Vehicles: 2015 Q5 3.0T Stg 2+, 2012 CW Golf R OEM+, 1983 Rabbit GTI Sport, 1969 Transporter Hello little buddy! Glad to finally have this in the car. Now the oil and coolant are on separate channels and there is a t-stat in place for the cold winter mornings. Thanks to Greg at TyrolSport for the bracket and Issam at INA for the oil cooler kit.



paypal.me/waterwerks

Reply With Quote

#524



 Join Date:
 Jun 28th, 2000


 Location:
 Colorado Springs, CO

 Posts:
 6,028

 Vehicles:
 2015 Q5 3.0T Stg 2+, 2012 CW Golf R OEM+, 1983 Rabbit GTI Sport, 1969 Transporter
 Hello small weekend project! The ultimate in automation for or driving experience (in a MK6 Golf R that is) As always...thanks to Peter for the parts and info.

Once this is complete I'll have a pair of internal OEM auto dimming mirrors available to anyone that wants to retrofit this option to your Mk5/6 vehicle. One will be a 5 pin mirror (internal and driver exterior mirror only) and the other will be a 6 pin mirror which will allow for internal as well as the driver and passenger external auto dimming mirror glass to be added.





PwrUsr •

Member	
Join Date:	Aug 1st, 2015
Location:	Maryland
Posts:	442
Vehicles:	2017 GTI Sport 6mt

� Originally Posted by flieger 💵

This makes the top 5 of my interior list for things I'm super happy about. When all was said and done, it took way longer to accomplish with having to get a custom shift boot made. But I'm very happy with how it turned out.


08-01-2015 02:35 AM

#525

Reply

BFI Heavy Weight Shift Knob - custom black Alcantara wrap w/black anodized knob and Alcantara shift boot.





For advertising information click HERE

+ Reply to Thread

« Previous Thread | Next Thread »

Forum	VW Model-Specific Forums	Golf VI R	Flieger's Golf R Build

You may post new threads	BB code is On	^
You may post replies	Smilies are On	
You may not post attachments	[IMG] code is On	
You may edit your posts	[VIDEO] code is On	
	HTML code is Off	

Forum Rules

Contact Us Archive Privacy Statement Terms of Service Top

All times are GMT -4. The time now is 01:48 PM.

Powered by <code>vBulletin</code> Version 4.2.2 Copyright © 2017 vBulletin Solutions, Inc. All rights reserved.

vBulletin Optimisation provided by vB Optimise v2.6.3 (Pro) - vBulletin Mods & Addons Copyright © 2017 DragonByte Technologies Ltd. vBulletin Security provided by vBSecurity v2.2.2 (Pro) - vBulletin Mods & Addons Copyright © 2017 DragonByte Technologies Ltd. Digital Point modules: Sphinx-based search

Terms of Use